



METALLIC



PU



290°F



PEEL : COLD



Flex Blade 45°
Medium Pressure



60 µm



15 Sec

SPECIFICATIONS

APPLICATION

1. Cut the material in reverse with a regular blade
Film blade required (90-100gf)
2. Weed the excess material
3. Heat press on the garment at 290°F & Protect the polyester carrier with silicone paper 15 sec - medium pressure
4. Peel the carrier off when cold

THICKNESS:  Polyurethane 60 microns

CARRIER: Adhesive & Transparent polyester



APPLIES ON

Cotton • Polyester • Acrylic & Similar Fibres

CARE & MAINTENANCE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

WASH

- Cold hand washing only
- Preferably inside out
- Do not bleach
- Tumble-dry unapproved
- Dry-cleaning unapproved

STORE

- Up to 1 year
- In a dry room (60-85°F)
- Away from sunlight
- In vertical position



800.253.1569 | wensco.com



NOTE: For best results, it is recommended to TEST prior to starting standard production